



ASA-51-7

Engine Log #2

10118\$P

Engine Record General Information

Manufacturer LYCOMING Model O-540-J3C5D

Serial L-23808-40A Type Certificate _____

This engine is currently installed in aircraft R-182 10118\$P S/N R182 00115

Minimum Octane Fuel _____ Oil Grade: Summer _____ Winter _____

Magneto Time _____ Point Setting _____ Firing Order _____

Spark Plug Gap _____

Manufacturer recommended overhaul at _____ hours

DATE 19 99	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5-1-99	TACH TIME	4943.8 HRS.	ETTSMOH 1814.6 HRS.	
				100HR INSPECTION COMPLETED THIS DATE 5-1-99 CHANGED OIL & FILTER. OIL 50WT AEROSHELL, FILTER CHAMPION CK48103. CHANGED SPARK PLUGS WITH NEW CHAMPION RHM38E. CHECKED MAG TIMING. COMPRESSION TEST #1 12/80 #2 12/80 #3 12/80 #4 12/80 #5 12/80 #6 12/80. ENGINE TEST RUN & LEAK CHECK SATISFACTORY.
				The aircraft airframe, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent of the repair are on file at this repair station under W/O no. 60921
				Date 5-1-99
				Signed <i>[Signature]</i>
				For Wipaire, Inc. CRS No. FJWR390K

©ASA 1993

DATE 19 97	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5-21-97	Tach	4768.4	TSMOH 1840.2	Changed oil & oil filter. Checked old filter OK this date. Took oil sample - added aeroshell 100W. Ground run OK.
				Ronald Harey A1 P1459140
				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108

©ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6-16-97	Tach 4799.0			① Changed oil & Filter, Inspected Filter, NO contaminants found, serviced with 8qts Aeroshell AS100W. J.D. Comeline, APO33845335

© ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-24-97	Tach 4841.3	TSMOH 1913.1		100hr Insp Comp this date. Changed oil & oil filter. Cut open old filter OK this date. Took oil sample - Comp checked. ① 74hp ② 72hp ③ 76hp ④ 76hp ⑤ 78hp ⑥ 72hp. Cleaned, gapped tested & rotated spark plugs. Replaced induction air filter. Added Aeroshell 100W oil Ground Run OK.
I CERTIFY THAT THIS ENGINE HAS				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108
BEEN INSPECTED IN ACCORDANCE WITH				
A 100hr INSPECTION AND WAS				
DETERMINED TO BE IN AN AIRWORTHY CONDITION.				
RONALD L. HARVEY A & P - 155104 5018-15-210 <i>Ronald L. Harvey</i>				

© ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
8-12-97	Tach	4871.7	TSMOK 1943.5	Changed oil & oil filter cut open old filter OK this date. Took oil sample. added deroshell 100W. Ground run OK Ranald L Harcey AIP1459140
				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108
8-27-97	Tach	4893.2	TSMOK 1964	Changed oil & oil filter cut open old filter OK this date. Took oil sample. added deroshell 100W. Ground run OK Ranald L Harcey AIP1459140
				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108

© ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9-23-97	Tach	4912.1	TSMOK 1988.9	Changed oil & oil filter cut open old filter OK this date. Took oil sample added deroshell 100W. Ground Run OK Ranald L Harcey AIP1459140
				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108

© ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
11-5-97	Tach	4947	100 hr	Inspection completed the TSMOH 20188 date changed oil & oil filter. Took oil sample. Compression check OK (1) 74/80 (2) 74/80 (3) 74/80 (4) 74/80 (5) 74/80 (6) 74/80. Cleaned, gapped, tested & rotated spark plugs - Replaced L inductive air filter. Added AeroShell 100W. Ground run OK -
I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.				ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108
Ronald L. Harcey RONALD L. HARCEY A & P 1450140				Ronald L. Harcey

©ASA 1993

DATE 19__	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
12-9-97	Tach	4973.5	TSMOH 2045.3 T.T. 4343.3	Removed this Eng from C/R-182 S/N R18200115 N118SP for Overhaul. Ronald L. Harcey A P 1459140
ST. PAUL FLIGHT CENTER 270 Airport Rd. St. Paul, MN 55107 612-227-8108				
2/4/98			4343.3	New log book started following a major overhaul at: Ref. WO# 14917 M. D. Lutz for DC2R763K
Custom Airmotive, Inc. FAA REPAIR STATION #DC2R763K AIRCRAFT ENGINE SERVICE 2702 N. SHERIDAN, BLDG. B TULSA, OK 74115 (918) 836-6836 FAX (918) 836-9431				

©ASA 1993

ir
T
id
to
Jed
2