

Date	N15T Beech Baron Maintenance Event	Logbook #	337 Approval Date
04/13/67	Removed Left Engine S/N CS155267 and installed factory remanufactured engine S/N 92430-6-L-R at 1,916.5 hrs.	Log Book 1	
11/28/67	Overhauled propeller S/N 633405 and 633406 coleted wirh McCauley service bulletin #62. Props checked and balanced.	Log Book 1	
07/18/68	Replace directional gyro S/N 241 with S/N 583.	Log Book 1	
09/30/68	Replaced right propeller Serial #633405 with Serial #: 652380 with TSO of 677 hrs on right enginr. Replace lower beacon with Wheeler Strobe. Installed new overhauled airspeed indicator. Replace PN-101 directional gyro and power supply as returned by manufacturer.	log Book 1	
01/19/70	Installed new hobbs a/c 3884.56	Log Book 1	
11/11/70	Engine CS91901-5-L installed on right side at hour meter 160.7 A/C 4,045.2	Log Book 1	
12/11/71	Both McCuley props S/N 712504 and 712507 overhauled. Hobbs:310.5 / Total Airframe 4,195 hrs.	Log Book 1	
10/19/73	Replace left fuel cell with new cell and repair right fuel cell.	Log Book 1	
11/27/81	Installed rebuilt Tach - 5588 hrs total	Log Book 2	
06/05/93	Rplaced Hobbs - old reading 2,103.3 New reading 0 hrs - Total Time: 5,989.2 hrs	Log Book 2	
11/8/1094	Installed facory rebuilt IO-470-L26B engines on both sides Rt: S/N: 297504-R Lt S/N: 297503-R Engine 0 Time. Tach 82 hrs	Log Book 2	
02/16/95	Installed vortex generators on the wing and vertical tail and strakes on the engine nacelles in accordance with drawing list MA2005 and installation instructions MA2004, per STC 3: SA5789NM.	Form 337	2/16/1995
09/15/95	Replace all landing gear seals	Log Book 2	
07/20/96	Both prop govoners O/H and reinstalled	Log Book 2	
03/25/99	Installed completely overalled L/R Props at Tach 0130 hrs	Prop Books	
02/25/02	Both Aux fuel pumps rebuilt and reinstalled -- rplaced right aux fuel tank	Log Book 2	
02/23/06	Removed and replaced right wing leading edge section / installed Vortex Grnerators Tach: 752	Log Book 2	2/23/2006
08/01/14	Last full inspection Total time: 6908.7 Hobbs 1,119.3	Log Book 2	
09/04/17	Transonder Test and flight inspection	Log Book 2	
09/04/17	Both Engines have 1,041.7 hrs since new	Engine Log	

Best attempt has been made to reflect accurate information, "Subject to Verification by the Buyer"

