

Date	N5400B Maintenance Event	Logbook #	337 Approval Date
06/08/56	Airworthiness Certificate	Registration	
11/30/56	Installed Horizon Gyro, Turn and Bank Indicator and modified with w Sensitive altimeter	A/C Log #1	
02/04/57	Complete custom radio installation. Refer to Form #337 this date for detailed information.	A/C Log #1	02/04/57
08/28/57	Removed and install new battery. Refer to Form #337 this date for detailed information. Tach: 102.7	A/C Log #1	08/28/57
01/27/58	Added R-30 Receiver, replaced Sonotone battery with Reading R-33 battery, installed Narco Mark II Omnigator and Narco V12MP2A Power Supply.	A/C Log #1	01/27/58
03/24/59	Made major structural repair to outer wing caused by gust of wind. Refer to Form #337 dated 3/26/59 for detailed information.	A/C Log #1	03/26/59
12/08/59	Installed Globe Gyro-Stabalizer. Refer to Form #337 dated 12/3/59 for detailer information.	A/C Log #1	12/03/59
03/04/60	Installed Richter Aero Equipment type B-5 Carburetor Temp Probe. Refer to Form #337 this date for detailed information. Tach: 481	A/C Log #1	03/04/60
10/02/63	Left wing repaired, ailerons replaced and other work. Refer to Form #337 this date for detailed information.	A/C Log #1	10/02/63
03/11/64	Replaced all seat belts and instrument panel shock mounts. Tach: 854.9	A/C Log #1	
04/27/70	Original Engine (s/n 66331-6-L) Removed and replaced with overhauled O-470-L, s/n 48356-8-K-L. Replaced bushings and bolts on nose scissors, replaced nose steering rod-ends, replaced flap cables in cabin section under the floor and installed Rebate battery R-35. Tach/TT: 927.4, TSOH: 0.0, ETT: 1568.0	A/C Log #1 Engine Log #1	
07/22/70	Installed Narco MK-12 Comm. Refer to Form 337 this date for detailed information.	A/C Log #1	07/22/70
02/03/75	Installed overhauled artificial horizon and overhauled D.G. Tach: 1143	A/C Log #1	
06/11/76	Repaired and repainted spinner. Tach: 1218	A/C Log #1	
09/08/77	Installed artificial Horizon. Tach: 1278	A/C Log #1	
03/25/80	New Tach installed. Old Tach/ TT-1333.0, New Tach: 0.0	A/C Log #2	
07/03/80	Removed Narco MK-2 Nav/Com, installed King KX-170B with KI-201C and KT-78A transponder.	A/C Log #2	
06/07/81	Installed new spinner dome and painted new dome. Reworked both elevators and reinforced outboard hinges. Tach: 26.0, TT: 1359.0	A/C Log #2	
06/14/82	Installed all new instrument panel mounts, new door hinges and new landing light. Tach: 64.0, TT: 1397.0	A/C Log #2	
	Removed Gyro-Stabalizer.	A/C Log #2	01/15/85
11/04/88	Aircraft stripped to bare metal, treated and repainted. Tach: 202.8, TT: 1535.8	A/C Log #2	
	Installed Brackett Air Filter model BA 8110 in accordance with Brackett iinstallation instructions.	A/C Log #2	07/01/89
07/01/89	Removed engine s/n 48356-8-K-L and Installed overhauled engine 48356-8-K-L Tach: 212.8, TT: 1588.0, ETT: 2186.8	A/C Log #2 Engine Log #2	
01/08/90	Installed ACK-30 encoder. Refer to Form 337 dated 1/11/90 for detailed information.	A/C Log #2	01/11/90

06/25/90	Replaced with new airspeed, rate of turn, manifold and D.G. indicators. Removed Narco MK 12 and installed new Narco NAV 122 and COMM 120. Tach: 236.81, TT: 1569.81	A/C Log #2	
03/19/91	Removed ARC R-30 ADF system and installed King KR-86 ADF. Refer to Form #337 this date for detailed information. Tach: 319.2	A/C Log #2	03/19/91
03/22/91	Removed King KR-86 ADF system and replaced with King ADF KR-87 system. Refer to Form #337 this date for detailed information. Tach-319.2	A/C Log #2	03/22/91
04/17/91	Installed Cleveland Wheel and Brake assemblies. STC SA13GL. Refer to Form #337 this date for detailed information. Tach: 341.62, TT: 1674.62	A/C Log #2	04/17/91
06/24/92	Installed Graphic Engine Monitor System Model GEM-602 in accordance with Insight Instrument Corporation's manual "Installing the G.E.M."	A/C Log #2	06/24/92
05/31/94	Removed Telex TC-200 intercom system and installed PS Engineering PM 1000 four place intercom system. Advisory Circular 43.13-2A. Tach 636.04	A/C Log #2	05/31/94
08/27/97	Installed new Airtex headliner, seatbelts, soundproofing and carpet. Installed lumbar supports for pilot, co-pilot seat, glareshield and various panels in accordance with FAR 23.853.	A/C Log #2	08/27/97
03/07/98	Installed replacement windshield Tach; 788.43, TT: 2121.43	A/C Log #2	
06/09/99	Removed Hartzell propeller, propeller governor, and spinner assembly. Installed McCauley propeller model D3A36C435/80VEA-0, Propeller governor model 290D3-M/T1 and spinner assembly. STC# SA00819CH	A/C Log #2	06/09/99
10/05/99	Removed McCauley propeller and spinner assembly. Installed McCauley Propeller Model 2A34C203/G-90DCA-8 and spinner assembly. STC# SA01033CH Tach: 851.0, TT: 2184.0, Prop Since New: 0.0	A/C Log #2 Prop Log #1	10/05/99
01/01/14	Installed new throttle control assy Tach: 1252.56	A/C Log #2	
04/25/15	Installed Dynamic Propellers carburetor heat air box top skin. STC# SA02425SE. Installed Dynamic Propellers support brackets. STC# SA00740SE	A/C Log #2	04/23/15
04/25/15	Installed modified exhaust collector assembly STC# SA01293LA. Installed Whelen LED Nav light assys Tach:1281.19, TT: 2614.8	A/C Log #2	04/23/15
08/09/17	Replaced ELT w/Kannad Aviation 1001196, Engine removed and reinstalled after overhaul. Tach: 1325,75, TT: 2659.36, SMOH: 0.0, ETT: 3297.76	A/C Log #3 Engine Log #4	
12/21/17	Removed KT76A transponder. Installed Appareo Stratus ESG ADS-B OUT compliant transponder. STC# SA04112CH	A/C Log #3	12/21/17
12/29/17	Removed Generator and Installed SAL 12-70C alternator kit. STC# SA110682SC Tach: 1333	A/C Log #3	12/29/17
02/07/20	Propeller Repaired and reinstalled, Tach 1391.5, Prop TIS: 533.05	Prop Log #2	
08/12/20	Replaced Concorde battery Tach 1796.02	A/C Log #3	
11/06/20	Annual inspection, Tach 1411.43, TT: 2745.04	A/C Log #3	
11/06/20	Annual inspection, Tach 1411.43, Prop TIS: 552.98	Prop Log #2	
11/06/20	Annual Inspection, Compressions: 70, 70, 76, 72, 72, 72. Tach 1411.43, SMOH: 85.68, ETT: 3383.64	Engine Log #4	

Best attempt has been made to reflect accurate information, "Subject to Verification by the Buyer"