

HISTORICAL RECORD

RECORD OF ASSOCIATE EQUIPMENT

ARTICLE	MODEL	A. A. F. OR SERIAL No.	INSTALLED		REMOVED		DISPOSITION
			Date	Aircraft Time	Date	Aircraft Time	
Carburetor	MA35PA	3962620	10-20-55	00:00			
Magneto L	S6LN-20-21	27593510-20-55	10-20-55	00:00			
Magneto R	S6LN-20-21	284500	10-20-55	00:00			

REMARKS

Precede each remark with name of station and date.
Enter each accident which resulted in damage or was caused by engine failure.
Show cause and result.

AVCO 9-21-53 Gen Overhaul. Reason:
Tach. generator housing loose in access-
ory case and leaking oil. IT 1855:00
Hrs. Engine overhauled in accordance
with contract 33(600)31109. Engine
equipped with .010 oversize cylinders.

T.O. 2R-1-15 dated 15 Jan 54 Sec. 8,
Part XII & XIII C/W.

T.O. 2R-1-11 Sec. I and II dated 10-30-53
C/W.

Engine designation changed to 0-290-11
Per TWX SAMCE 10-8-E.

DAI 24 Oct 55

Insp.

RECORD OF TRANSFERS

RECEIVED BY AND SHIPPED BY		DATE	HOURS SINCE OVERHAUL	TOTAL HOURS	INSPECTED
Station	Organization				
Dallas Airmotive, Inc.		9-20-55	1047:00	1855:00	<i>[Signature]</i>
Dallas, Texas					
Dallas Airmotive, Inc.		Oct 24 1955	00:00	1855:00	<i>[Signature]</i>
Dallas, Texas					
SAAMA	Supply Div r	3 Nov 55	00:00	1855:00	<i>[Signature]</i>
56-N055691					
SAAMA	Supply Div s	10 Apr 58	00:00	1855:00	<i>[Signature]</i>
FOREST PARK, GA.	ACD TSS,	R 5 May 58	00:00	1855:00	<i>[Signature]</i>
FOREST PARK, GA.	ACD TSS,	S 13-16-58	00:00	1855:00	<i>[Signature]</i>