

# St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

**Shop Order: 9624**  
Acct Number: N2033X

**Opened: 9/01/2025**  
**Close Date: 2/27/2026**

Sold To: Wings Of Hope

<b>Aircraft Number:</b>	<b>N7048U</b>	<b>Type:</b>	<b>S/N:</b>
-------------------------	---------------	--------------	-------------

Eng#	Type	S/N	Time	Cycles	Prop Type	Prop S/N	Prop Time
1							

**Discrepancy: 1**

**Problem:**  
PICK UP AIRPLANE FROM KFYG.

**Action Taken:**  
C/W ABOVE.

Charges This Item:	6.25 Hours @	115.00	\$	718.75
	<b>Total For This Discrepancy:</b>			<b>\$ 718.75</b>

**Discrepancy: 2**

**Problem:**  
INSPECT FOR FERRY FLIGHT.

**Action Taken:**  
C/W ABOVE.

Charges This Item:	2.00 Hours @	115.00	\$	230.00
	<b>Total For This Discrepancy:</b>			<b>\$ 230.00</b>

**Discrepancy: 3**

**Problem:**  
R/H BRAKE FLAT.

**Action Taken:**  
SERVICED AT KFYG FOR FERRY FLIGHT

Charges This Item:	1.00 Hours @	115.00	\$	115.00
	<b>Total For This Discrepancy:</b>			<b>\$ 115.00</b>

**Discrepancy: 4**

**Problem:**  
100HR/ANNUAL INSPECTION DUE.

**Action Taken:**  
C/W ABOVE - TACH - 799.2

Charges This Item:	50.00 Hours @	115.00	\$	5,750.00
--------------------	---------------	--------	----	----------

Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
FORMULA 10-10	Solvent		1.00	Quart	13.000		13.000	\$ 13.00
05-01019	Filter		2.00	Each	15.000		15.000	\$ 30.00
B3-5-1	FILTER, VACUUM RELIEF		2.00	EA	5.000		5.000	\$ 10.00
B3-11-1	GASKET		2.00	EA	32.000		32.000	\$ 64.00
630979-9	O-RING		4.00	EA	3.500		3.500	\$ 14.00

## St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

M-674	Spark Plug Gasket		23.00	EA	1.300		1.300	\$	29.90
MS24694-S4	Screw		16.00	Each	0.250		0.250	\$	4.00
Total For This Discrepancy:								\$	5,914.90

<b>Discrepancy: 5</b>										
<b>Problem:</b> AD96-12-22 DUE.										
<b>Action Taken:</b> C/W BY VISUAL INSPECTION										
Charges This Item:					0.25 Hours @		115.00		\$	28.75
Total For This Discrepancy:								\$	28.75	

<b>Discrepancy: 6</b>										
<b>Problem:</b> AD96-12-22 DUE.										
<b>Action Taken:</b> C/W BY VISUAL INSPECTION										
Charges This Item:					0.25 Hours @		115.00		\$	28.75
Total For This Discrepancy:								\$	28.75	

<b>Discrepancy: 7</b>										
<b>Problem:</b> L/H ENGINE #6 BOTTOM SPARK PLUG LEAD.										
<b>Action Taken:</b> REPLACED WITH SERVICEABLE. OPS CHECK OK										
Charges This Item:					0.75 Hours @		115.00		\$	86.25
Total For This Discrepancy:								\$	86.25	

<b>Discrepancy: 8</b>									
<b>Problem:</b> L/H LANDING LIGHT INOP AND RETRACTED.									
<b>Action Taken:</b> SEE DISC #31									
Total For This Discrepancy: \$ N/C									

<b>Discrepancy: 9</b>										
<b>Problem:</b> STRIPPED SCREWS.										
<b>Action Taken:</b> NUMEROUS STRIPPED AND FROZEN SCREWS REMOVED WITH EXTRACTORS AND REPLACED										
Charges This Item:					10.75 Hours @		115.00		\$	1,236.25
Total For This Discrepancy:								\$	1,236.25	

<b>Discrepancy: 10</b>									
<b>Problem:</b> R/H OIL FILTER ADAPTER NUT HAS MARKS OF PREVIOUS DAMAGE.									
Total For This Discrepancy: \$ N/C									

<b>Discrepancy: 11</b>									
<b>Problem:</b> R/H SENDING UNIT SEEPING.									
<b>Action Taken:</b> CUSTOMER INFO. LIKELY FROM INACTIVITY. OK FOR SERVICE									
Total For This Discrepancy: \$ N/C									

## St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

<b>Discrepancy: 12</b>			
<b>Problem:</b> R/H VAC PUMP SHAFT BROKEN.			
<b>Action Taken:</b> DISCREPANCY LIST ITEM			
			Total For This Discrepancy: \$
			N/C
<b>Discrepancy: 13</b>			
<b>Problem:</b> R/H THROTTLE SHOWS SIGNS OF LEAKS.			
<b>Action Taken:</b> CUSTOMER INFO. LIKELY FROM INACTIVITY			
			Total For This Discrepancy: \$
			N/C
<b>Discrepancy: 14</b>			
<b>Problem:</b> R/H FUEL PUMP POWER WIRE BROKEN.			
<b>Action Taken:</b> REMOVED WIRE. REPLACED WITH SERVICEABLE WIRE AND SPECIAL CONNECTOR			
Charges This Item:	2.50 Hours @	115.00	\$ 287.50
			Total For This Discrepancy: \$ 287.50
<b>Discrepancy: 15</b>			
<b>Problem:</b> FUEL CAP ORING.			
<b>Action Taken:</b> REPLACED ORINGS.			
Charges This Item:	1.00 Hours @	115.00	\$ 115.00
			Total For This Discrepancy: \$ 115.00
<b>Discrepancy: 16</b>			
<b>Problem:</b> SEDIMENT IN L/H FUEL SCREEN.			
<b>Action Taken:</b> CLEANED SCREEN THOROUGHLY AND FLUSHED WITH PUMP			
Charges This Item:	1.00 Hours @	115.00	\$ 115.00
			Total For This Discrepancy: \$ 115.00
<b>Discrepancy: 17</b>			
<b>Problem:</b> ELT BATTERY EXPIRED.			
<b>Action Taken:</b> REPLACED BATTERY.			
Charges This Item:	0.25 Hours @	115.00	\$ 28.75
			Total For This Discrepancy: \$ 28.75
<b>Discrepancy: 18</b>			
<b>Problem:</b> RH ENGINE HAS CORRODED CAM AND LIFTERS			
<b>Action Taken:</b> OK FOR SPECIAL FLIGHT PERMIT PURPOSES			
			Total For This Discrepancy: \$
			N/C

## St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

<b>Discrepancy: 19</b>										
<b>Problem:</b> L/H RUDDER STOP BOLT BENT AND SAFETIED INCORRECTLY.										
<b>Action Taken:</b> PROPERLY SAFETIED.										
Charges This Item:					0.25 Hours @		115.00		\$	28.75
					Total For This Discrepancy:		\$		28.75	
<b>Discrepancy: 20</b>										
<b>Problem:</b>										
					Total For This Discrepancy:		\$		N/C	
<b>Discrepancy: 21</b>										
<b>Problem:</b> BOTH BRAKE ASSY LEAKING.										
<b>Action Taken:</b> CLEANED BRAKE ASSY, REMOVED ORINGS, INSTALLED NEW ORINGS ON BOTH MAINS.										
Charges This Item:					4.00 Hours @		115.00		\$	460.00
Part Number	Description			Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
MS28775-222	O-RING				6.00	EA	6.000		6.000	\$ 36.00
					Total For This Discrepancy:		\$		496.00	
<b>Discrepancy: 22</b>										
<b>Problem:</b> L/H FUEL SELECTOR SCREW HOLE STRIPPED.										
<b>Action Taken:</b> INSTALLED SCRE AND NUT. OK FOR SERVICE										
Charges This Item:					0.50 Hours @		115.00		\$	57.50
					Total For This Discrepancy:		\$		57.50	
<b>Discrepancy: 24</b>										
<b>Problem:</b> WHEEL BEARINGS NEED SERVICING.										
<b>Action Taken:</b> C/W ABOVE.										
Charges This Item:					5.00 Hours @		115.00		\$	575.00
					Total For This Discrepancy:		\$		575.00	
<b>Discrepancy: 25</b>										
<b>Problem:</b> SEDIMENT IN R/H FUEL STRAINER										
<b>Action Taken:</b> CLEANED SCREEN THOROUGHLY AND FLUSHED WITH PUMP										
Charges This Item:					1.00 Hours @		115.00		\$	115.00
					Total For This Discrepancy:		\$		115.00	
<b>Discrepancy: 26</b>										
<b>Problem:</b> BOTH BRAKES NEED TO BE BLED.										
<b>Action Taken:</b> BLED BRAKES AND TESTED										
Charges This Item:					1.50 Hours @		115.00		\$	172.50
					Total For This Discrepancy:		\$		172.50	

## St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

Discrepancy: 27									
<b>Problem:</b> SPARK PLUG RESISTANCE TEST FAIL ON L/H ENGINE.									
<b>Action Taken:</b> INSTALLED NEW SPARK PLUG ON L/H ENGINE.									
Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price		Extended
URHB32E	Spark Plug		1.00	Each	60.000		60.000	\$	60.00
Total For This Discrepancy:								\$	60.00
Discrepancy: 28									
<b>Problem:</b> R/H ENGINE AIR BOX LATCH LOOSE.									
<b>Action Taken:</b> OK FOR SERVICE									
Total For This Discrepancy:								\$	N/C
Discrepancy: 29									
<b>Problem:</b> R/H MAG TIMING OUT.									
<b>Action Taken:</b> RE-TIMED MAGS.									
Total For This Discrepancy:								\$	N/C
Discrepancy: 30									
<b>Problem:</b> LUBRICATION SERVICING.									
<b>Action Taken:</b> LUBRICATED AIRFRAME NOT COUNTING WHEEL BEARINGS									
Charges This Item:					1.25 Hours @		115.00	\$	143.75
Total For This Discrepancy:								\$	143.75
Discrepancy: 31									
<b>Problem:</b> L/H CIRCULATORY PUMP AND LANDING LIGHT/RETRACTION WORKING INTERMITTENTLY.									
<b>Action Taken:</b> TESTED FOR POWER AT SWITCH. HAS POWER. PUMP LIGHT AND RETRACTION WORKING AFTER TAPPING ON SWITCH BOX.									
Charges This Item:					1.50 Hours @		115.00	\$	172.50
Total For This Discrepancy:								\$	172.50
Discrepancy: 32									
<b>Problem:</b> DAMAGE AFT OF MAIN JACK POINTS.									
<b>Action Taken:</b> CUSTOMER INFO. OLDER DAMAGE. OK FOR SERVICE									
Total For This Discrepancy:								\$	N/C
Discrepancy: 33									
<b>Problem:</b> RIVET TAILS IN FLAP WELL AREA AT REAR SPAR.									
<b>Action Taken:</b> CLEANED AS MUCH AS WE COULD SEE									

## St. Charles Flying Service, Inc.

6016 Portage Road  
 Portage Des Sioux, MO 63373  
 636-946-6066  
 FAX 636-250-3098

		Total For This Discrepancy:	\$	N/C				
<b>Discrepancy: 36</b>								
<b>Problem:</b> RIVNUT BELOW R/H DOOR AT R/H WING ROOT.								
<b>Action Taken:</b> REPLACED RIVNUT.								
Charges This Item:		1.50 Hours @	115.00	\$ 172.50				
		Total For This Discrepancy:		\$ 172.50				
<b>Discrepancy: 37</b>								
<b>Problem:</b> FUEL STAINS ON R/H SENDING UNIT.								
<b>Action Taken:</b> CLEANED.								
Charges This Item:		0.50 Hours @	115.00	\$ 57.50				
		Total For This Discrepancy:		\$ 57.50				
<b>Discrepancy: 38</b>								
<b>Problem:</b> AD2004-21-05 DUE.								
<b>Action Taken:</b> C/W BY VISUAL INSPECTION								
Charges This Item:		4.25 Hours @	115.00	\$ 488.75				
		Total For This Discrepancy:		\$ 488.75				
<b>Discrepancy: 39</b>								
<b>Problem:</b> R/H ENGINE CRANK SHAFT CORROSION.								
<b>Action Taken:</b> CLEANED VISIBLE AREA OF CRANK AND CLEANED WITH SCOTCH BRITE TO TEST DEPTH AND AMOUNT OF CORROSION.								
Charges This Item:		1.00 Hours @	115.00	\$ 115.00				
		Total For This Discrepancy:		\$ 115.00				
<b>Discrepancy: 40</b>								
<b>Problem:</b> CORROSION INSIDE OF NOSE COMPARTMENT.								
<b>Action Taken:</b> CLEANED TO VERIFY EXTENT								
Charges This Item:		0.75 Hours @	115.00	\$ 86.25				
		Total For This Discrepancy:		\$ 86.25				
<b>Discrepancy: 44</b>								
<b>Problem:</b> HEATER INACTIVE FOR 5 YEARS								
<b>Action Taken:</b> PERFORMED HEATER DECAY PRESSURE TEST DUE TO INACTIVITY. TESTED HEATER								
Charges This Item:		2.00 Hours @	115.00	\$ 230.00				
		Total For This Discrepancy:		\$ 230.00				
Part Number	Description	Credit	Quantity	Units	List Price	Disc	Unit Price	Extended
M25988-1-232	Oring		4.00	Each	11.000		11.000	\$ 44.00
<b>Miscellaneous Charges:</b>							Misc Supplies:	\$ 417.20

# St. Charles Flying Service, Inc.

6016 Portage Road  
Portage Des Sioux, MO 63373  
636-946-6066  
FAX 636-250-3098

<b>Summary:</b>					
-----------------	--	--	--	--	--

Total Parts:	\$	291.90	Total Oil:	\$	13.00
Misc Supplies:	\$	417.20	Total Labor - 101.00 Hours:	\$	11,615.00

<b>Totals:</b>					
----------------	--	--	--	--	--

<b>SubTotal:</b>	\$	<b>12,337.10</b>
<b>Total Charges:</b>	\$	<b>12,337.10</b>
<b>Amount Remaining:</b>	\$	<b>12,337.10</b>

THANK YOU!  
WE APPRECIATE  
YOUR BUSINESS!

All VIP members must have account paid in full within 30 days to maintain VIP status.

CHECK OUT OUR WEBSITE AT  
[WWW.STCHARLESFLYINGSERVICE.COM](http://WWW.STCHARLESFLYINGSERVICE.COM)