

Date	N7937P Maintenance Event	Logbook #	337 Approval Date
12/21/62	Airworthiness Certificate	Aircraft Log	
01/08/63	Original Avionics Install	Aircraft Log	01/12/63
11/25/66	Gear Up Landing Repairs	Aircraft Log	11/25/66
08/21/70	Radio & Transponder Install	Aircraft Log	08/21/70
01/07/75	Installed Rudder Balance Wts	Aircraft Log	01/07/75
11/06/75	Engine O-540-A1D5, s/n RL-9114-40 Remanufactured @ Lycoming	Engine Log	
03/25/76	Engine Swap for a Remanufactured Engine, s/n RL9114-50, Tach/TT: 1419.0, SMOH: 0.0	Engine Log	
07/26/76	Avionics Change to Collins	Aircraft Log	
02/10/77	DME Install	Aircraft Log	
10/02/79	Century IIB A/P Install	Aircraft Log	
06/28/90	Replaced Vertical Fin	Aircraft Log	
09/27/91	Prop O/H @ Sensenich, Prop TSOH: 0.0	Prop Log	
10/27/91	Prop Intalled, Tach/TT: 2189.0, Prop SOH: 0.0	Prop Log	
11/22/91	LORAN & KX-155 Install	Aircraft Log	11/22/91
08/04/03	LORAN removed, Garmin 530 and KX-155 Install	Aircraft Log	08/04/03
06/16/14	Prop Recurring AD C/W 97-18-02 R1, Tach/TT 2298.58	Prop Log	
08/11/14	Webco Door Latch Install, STC 2549CE	Aircraft Log	08/11/14
10/28/14	Sky-Tec Starter Installed	8130-3	
06/21/16	Last Annual Inspection, Tach/TT: 2305.5 SMOH: 886.5 Compressions: 60, 60, 70, 74, 75, 65	Aircraft Log	

Best attempt has been made to reflect accurate information, "Subject to Verification by the Buyer"