08/18/17 Ta	N618PM Builder's Flight Log First Flight, Heavy Aft Stick pressure, Added 8 lbs to tail	Flight Time	Total
08/01/17 Fi 08/18/17 Ta		Flight Time	
08/18/17 Ta	irst Flight Heavy Aft Stick pressure Added 8 lbs to tail		Time
	istright, freavy fite sterk pressure, fluded o los to tall	1.2	1.2
08/27/17 A	ail too light	3.7	4.9
	Added 6 lbs to tail, Fixed Radio Ground, Added Elevator Gap Tape	0.7	5.6
09/04/17 H	Heavy Left Wing	1.1	6.7
09/11/17 Fi	ixed Heavy Left Wing	0.4	7.1
09/17/17 H	Heavy Left Wing	1.5	8.6
09/18/17 Fi	ixed Heavy Left Wing	0.6	9.2
10/03/17 F	lew Wings Level	0.8	10.0
10/04/17 O	Dil Change, Added 2.5 degree dihedral	0.9	10.9
10/11/17 FI	lys good, Indicates 110 @ 2350 RPM	1	11.9
04/25/18		1.7	13.6
05/01/18		2.1	15.7
06/01/18		0.6	16.3
06/06/18 A	All good, radio works	0.5	16.8
08/22/18		2.3	19.1
08/25/18		1.8	20.9
09/02/18		0.9	21.8
09/09/18 O	Dil Change	0.9	22.7
09/28/18		1.2	23.9
10/05/18		0.9	24.8
10/16/18		1.2	26.0
04/25/19		1.1	27.1
05/10/19		1.7	28.8
08/27/19		0.7	29.5
09/01/19		0.5	30.0
09/19/19		2.1	32.1
09/23/19		0.4	32.5
09/25/19		1.0	33.5
09/26/19		1.1	34.6
10/25/19 O	Dil Change	0.9	35.5
04/27/20		0.6	36.1
04/28/20		1.3	36.8
05/01/20 Fi	ix gas leak	0.4	37.2
07/13/21		3.0	40.2
	Phase! Sign off in logbook	2.6	42.8
	Adjust tappets (runs smooth)	1.2	44.0
10/19/21 O		0.3	44.3
06/03/22		1.5	45.8
07/15/22		0.5	46.3
07/30/22		0.5	46.8
05/23/23		1.7	48.5
	Dil Change, New Battery	1.0	49.5
08/05/23		1.9	51.4
08/13/23		0.8	52.2
	Dil Change, Annual	0.0	52.2
09/03/23 0	5.1 S.141.75() / Hilliadi	1.7	53.9

09/17/23		0.7	54.6
09/21/23	Increase dihedral 3/4" to 63" (love it!)	0.5	55.1
10/10/23		0.9	56.0
10/20/23		0.8	56.8
11/02/23		0.8	57.6
10/23/24	Sold by Estate, Wings removed and trailered from Iowa to Minnesota		
05/27/25	Photo after New Owner (Donor) reassembled and test flew in Minnesota	0.6	58.2
	Donor flight time	14.5	72.7
11/06/25	Donated to Wings of Hope and Ferry Flight to Missouri	5.2	77.9