




St. Charles Flying Service, Inc.
6016 Portage Rd.
Portage des Sioux, MO 63373
(636) 946-6066 (800) 447-6066

Date: 3/26/26
Wings Of Hope
Mike Piccirilli

This is the list of discrepancies and un-airworthy items per 14CFR43.11 (a)(5) for N7048U Cessna 310N
S/N 310N-0171

1. RH Vacuum pump shaft sheered
2. Some corrosion on Airframe (nothing structural noted at this time)
3. Canvas cover torn in nose compartment
4. RH engine #1 cylinder 38/80 compression
5. RH engine corroded, including cam, lifters, crank counterweights (accessed through oil fill tube)

Respectfully,


Clinton A Grant AP494864959IA
DOM St Charles Flying Service
cagrnt01@yahoo.com