			337
			Approval
Date	N7904X Maintenance Event	Logbook #	Date
03/09/61	Airworthiness Certificate	A/C Log #1	
04/20/72	Install Overhauled original Engine, Tach/TT: 1423.0	Engine Log #1	
6/1/77	Installed Flap Gap Seal per STC SA3105WE	A/C Log #1	6/1/77
06/01/77	Aircraft Repainted (Thermal Aircraft Co, CA)	A/C Log #1	, ,
06/02/81	Last Entry of Aircraft Log Tach/TT: 1725	A/C Log #1	
05/08/88	Installed Auto Fuel STC SA1948CE	A/C Log #2	5/11/88
	Removed SLICK 664 magnetos and installed SLICK 6364 Magnetos per STC SE1220GL	Engine Log #2	10/10/96
12/11/96	Last Engine Log Entry, Tach/TT: 1964.02	Engine Log #1	
11/10/97	Initial Engine Log Entry, Tach/TT: 1986.63	Engine Log #2	
6/11/98	Spin On Oil Filter Installation per SE8409SW	Engine Log #2	6/11/98
04/16/99	Removed Edo-Aire RT 563A Nav/Com and Genave 1000 Nav/Com. Installed KX-155 & KX 125 NAV/COMs, Apollo 618 Loran C and Sigtronics SPA 400 Intercom.	A/C Log #2	4/15/99
03/30/04	Replaced original prop with overhauled prop, SPOH 0.0, Tach/TT: 2334.5	Prop Lob #1	
02/05/05	Removed Cylinder #2 and replaced w/repaired cylinder Tach/TT: 2423.1	Engine Log #2	
04/18/05	Installed Monroy ATD-300 Air Traffic Detector, Tach/TT: 2431.5	A/C Log #2	
02/19/06	Replaced Rt & Left Mags, Tach/TT: 2457.7	Engine Log #2	
07/20/08	Replaced Headliner Tach/TT; 2571.2	A/C Log #2	
04/08/10	Removed Carb Temp Indicator to install EI Fuel Flow Indicator per STC SA00068SE	A/C Log #2	4/8/10
07/01/10	R/R Muffler Tach/TT: 2670.6	Engine Log #2	
07/17/11	Last Annual Inspection Tach/TT: 2698.5	A/C Log #2	
		Engine Log #2	
		Prop Log #1	
10/25/11	Replaced rotating beacon with Whelen LED beacon per STC SA615EA	A/C Log #2	10/25/11
10/25/11	Replaced NARCO ELT 10 with ACK E-04 ELT	A/C Log #2	10/26/11
10/26/11	Replaced GE 4509 Taxi/Ldg lights with Knots 2U HID lamps per STC SA01834CH Tach/TT: 2718.1	A/C Log #2	10/26/11

Best attempt has been made to reflect accurate information, "Subject to Verification by the Buyer"