

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

1. Approving Civil Aviation Authority/Country: FAA/United States		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Traveling Number: PRP17-03206
4. Organization Name and Address: Aircraft Specialists, Inc. 6005 Propeller Lane Sellersburg, IN 47172		Repair Station # PZ4R458M		5. Work Order/Contract/Invoice Number: PRP17-03206	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	McCauley Propeller	1C172/EM7653	1	73430	Repaired
12. Remarks: Repitched propeller from 50" pitch to 53" pitch. All work performed in accordance with McCauley manual 730720 Rev. 6 dated 12/2002.					
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval/Authorization No.:	14b. Authorized Signature: 		14c. Approval/Certificate No.: PZ4R458M
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Jeff Davis		14e. Date (dd/mm/yyyy): 08 JAN 2018
User/Installer Responsibilities					
<p>It is important to understand that the existence of this document does not automatically constitute authority to install the aircraft engine/propeller/article.</p> <p>Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					

FAA Form 8130-3 (02-14)

NSN: 0052-00-912-9935

SUB-TOTALS this page

TOTALS-Carry forward to next page

DATE <i>2010</i>	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
<i>2010</i>	<i>5204.8</i>	<i>0.0</i>	<i>20.3</i>	TOTALS brought forward from previous page
<i>02-15-2011</i>	<i>5212.0</i>	<i>7.0</i>	<i>27.5</i>	<p>I certify this <u>PROPELLER</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an airworthy condition. Date <u>02-15-2011</u> Tach <u>27.5</u> INSP. PROP. NO DEFECTS NOTED.</p>
<i>05-09-2012</i>	<i>5216.4</i>	<i>12.2</i>	<i>31.9</i>	<p>I certify this <u>PROPELLER</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an airworthy condition. Date <u>05-09-2012</u> Tach <u>31.9</u></p>

R. Hueto IA263341646

Aviation A&P 266751561 IA.

9 December 2020 Tach. 5962.0 ACT. 6070.0

N: 2585L

Propeller Model: McCauley 1C172-EM7650

SN: 73430

Maintenance:

1. Installed this propeller on N2585L Cessna 172H, SN: 55785.

I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Date: 9 December 2020



Gerardo Morales A&P 3540227 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page

THE **adlog**TM AIRCRAFT
MAINTENANCE
RECORDKEEPING
SYSTEM

Prop 1

**PROPELLER
MAINTENANCE
RECORDS**

PROPELLER MAINTENANCE RECORDS

Log No. 1

Aircraft Registration No. N-8252X

Propeller Manufacturer MCCAWLEY

Hub Model RA-1C172 EM 7650 ~~7650 RA~~

Blade Design No. _____

Hub Serial No. 73430

Blade Serial No's.

1. _____
2. _____
3. _____
4. _____

Pitch Range:

High 50 Low _____

Feather _____ Reverse _____

Governor Manufacturer NA

Model No. _____

Serial No. _____

Date installed on aircraft 01-22-1985 TTL9803

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- Right Left
 Front Rear

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

www.adlog.com
PO BOX 1359 / SOUTHOLD, NY 11971-0965
(631) 765-9375
1-800-235-6444
FAX: (631) 765-9359

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
01-12-2009	5204.8		00:00	<p>I certify this <u>PROPELLOR</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an <u>airworthy condition</u> . Date <u>01-12-2009</u> Tach <u>00:00</u></p> <p>NOTE: PROP. OVERHAUL @ JTT 2980.3 ON 03-22-1985 R. H. W. I.A. 267341646 PROP REMOVED FOR OIL RTR</p>
02-15-2010	5204.8	0.0	20.3	<p>I certify this <u>PROPELLOR</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an <u>airworthy condition</u> . Date <u>02-15-2010</u> Tach <u>20.3</u></p> <p>REINSTALLED PROP AFTER OVERHAUL AT SUNSTATE PROPELLER INC. REPLACED MOUNT BOLTS 6 EA AN8-43A + 6 NUTS UN13090910-27. TORQUE BOLTS TO SPEC'S. OPS OK EW.</p> <div style="border: 1px solid black; padding: 5px; margin: 10px 0;"> <p>Sunstate Propeller, Inc. 5110 West Grace Street Tampa, FL 33607 1-800-226-1089 OVERHAUL OF THIS PROPELLER MODEL: 1C172/EM7650 SERIAL # 73430 Completed on this Date: <u>02-09-2010</u> and was returned to service under work order # 16423</p> <p>Signature <u>[Signature]</u> 2330469</p> </div> <p style="text-align: right; margin-top: 20px;">R. H. W. I.A. 267341646</p>
5204.8 0.0 20.3				SUB-TOTALS this page
				TOTALS-Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
2009				TOTALS brought forward from previous page
01-12-2009	52048		00:00	<p>I certify this <u>PROPELLOR</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an <u>airworthy condition</u>.</p> <p>Date <u>01-12-2009</u> Tach <u>00:00</u></p> <p>NOTE: PROP. OVERHAULED @ JTT 2980.3 ON 03.22.1985</p> <p><i>[Signature]</i> IA267341646</p> <p>PROP REMOVED FOR OIL RITE</p>
02-15-2010	52048	0.0	20.3	<p>I certify this <u>PROPELLOR</u> has been inspected in accordance with an <u>ANNUAL</u> inspection and found in an <u>airworthy condition</u>.</p> <p>Date <u>02-15-2010</u> Tach <u>20.3</u></p> <p>REINSTALLED PROP AFTER OVERHAUL AT SUNSTATE PROPELLER INC. REPLACED MOUNT BOLTS 6 EA AN8-43A + 6 NUTS PN130909N-27. TORQUE BOLTS TO SPEC'S. OPECU CW.</p>
				<p>Sunstate Propeller, Inc. 5110 West Grace Street Tampa, FL 33607 1-800-226-1089</p> <p>OVERHAUL OF THIS PROPELLER MODEL: 1C172/EM7650 SERIAL # 73430 Completed on this Date: <u>02-09-2010</u> and was returned to service under work order # 16423</p> <p>Signature <i>[Signature]</i> 2330469</p>
				<p><i>[Signature]</i> IA267341646</p>
				<p>SUB-TOTALS this page</p>
52048	0.0	20.3		TOTALS—Carry forward to next page