

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-29-83		Overhauled propeller Hartzell model 1 HC. C24F-2CKF SN AN 1197 ALL manufactures service Letters, service bulletins AND FAA Airworthiness directives have been complied with on propeller only New Hub bolts installed	MEMPHIS PROPELLER SERVICE, INC. FAA APPROVED REPAIR STATION 710-21 W. J. 2329189

AVIATION PROPELLERS INC. SERVICEABLE TAG

CUSTOMER GOLDEN ISLES AVIATION, INC. DATE 10/19/88

MODEL BHC-C2YF-2CKF/FC8459-8R SERIAL NO. AN1197

REMARKS DISASSEMBLED, DESLUGGED, INSPECTED, REPAIRED, AND REASSEMBLED I/A/W F.A.A. AND MANUFACTURER SPECIFICATION

SB 142B c/w ANGLES LOW 14.4 REV. FEA 81.5
BLADE S/N C73778 C73835

WORK ORDER 4663A INSPECTOR *[Signature]*

INSTALLED ON POSITION DATE

SIGNATURE

DATE

3-13-89

PROP, INC.

Run up checks

ANNUAL/100 HR INSPECTION AND HAVE FOUND IT AIRWORTHY

TACH 30334/1000H TT LAR

DATE 12-9-88 *[Signature]*
210525801A

SERVICEABLE TAG

Northwest Propeller Service, Inc.

2131 E. St. N.E. • Auburn, WA 98002

REPAIR STATION NO. S61-89

T.S.O. *cc:cd* T.T.

MFG. *Hamilton*

MODEL NO. BHC2YF-2CKF

SERIAL NO. AN1197

BLADE MOD. NO. FC8459-8R

BLADE SERIAL NO. 1 C73778

2-13835 3. - 4. -

REMARKS: Complete overhaul of propeller per Hamilton manual #1170, & #1330. Installed #1170, & #1330. *[Signature]*
new decision best per H.S. 2, C/A AD 17-12-26, & Hamilton S/S 5#1180, #1360, #151A, & #105, & S/I #144E.

MECHANIC *Paul J. Borkland*

DATE 1-13-89

DATE

3-13-89

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE	DATE
4-10-89		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>PM</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>100</u> TACH TIME <u>3133</u> 1A 1532953 <u>Ronald J Wright</u>		10
6-23-89		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>PM</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>200</u> TACH TIME <u>3223</u> 1A 1532953 <u>Ronald J Wright</u>		2-

18

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10-16-89		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>PLN</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 300 TACH TIME 339.9 1A 1522953 Ronald D Wright	
2-19-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>PLN</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 400 TACH TIME 343.8 1A 1522953	

19

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-12-90			
		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>50111</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>452.5</u> TACH TIME <u>348.7</u>	
		1A1522953	
		<i>Small G. Wright</i>	
7-11-90		100H40	
		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>100H40</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>503.0</u> TACH TIME <u>3540.0</u>	
		5400. 1A1522953	
		<i>Small G. Wright</i>	

20

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
9-17-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>50111</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>553.6</u> TACH TIME <u>3590.6</u>	
		1A1522953	
		<i>Small G. Wright</i>	
12-1-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>100H12</u> INSPECTION AND WAS DETERMINED TO BE IN AIR WORTHY CONDITION. TOTAL TIME <u>604.92</u> TACH TIME <u>3641.92</u>	
		1A1522953	
		<i>Small G. Wright</i>	

21



Memphis Propeller Service
FAA Approved No. 710-21
Dewitt Spain Airport
2787 N. Second St.
Memphis, Tenn. 38127

Customer Silver Eagle Aircraft Inc

Item Hartzell Propeller

Model HC-C24F-2CKF

Serial Number AM 1197

"The propeller, or component above
was **OVERHAULED** and inspected in
accordance with current Regulations
of the Federal Aviation Agency and
is approved for return to service."
Details of the work accomplished on
file at this repair station.

W/O 3598 Date 11-29-88

Signed William J. Jones

Authorized Signature

OVERHAUL