

Old
Log

TRW HARTZELL PROPELLER OWNER'S MANUAL AND LOG BOOK

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-29-83		OVERHAULED propeller Hartzell model HC-C24F-2CLKF SN AN 1134	MEMPHIS PROPELLER SERVICE, INC. FAA APPROVED REPAIR STATION 710-211 VA Fye 2309189
		ALL MANUFACTURER'S SERVICE Letters, service bulletins and FAA Airworthiness directives have been complied with AS of this date on propeller only 11-29-83	
		New Hub bolts INSTALLED	

AVIATION PROPELLERS INC. SERVICEABLE TAG

CUSTOMER GOLDEN ISLES AVIATION, INC. DATE 10/19/88

MODEL BHC-C2YF-2CLKF/FJC8459-8R SERIAL NO. AN1134

REMARKS DISASSEMBLED, DESLUGGED, INSPECTED, REPAIRED, AND REASSEMBLED I/A/W F.A.A. AND MANUFACTURER SPECIFICATION

SB 142B c/w ANGLES LOW 14.4 REV. FEA 81.5
BLADE S/N C72744 C72698

WORK ORDER 4663A INSPECTOR *[Signature]*

INSTALLED ON POSITION DATE

SIGNATURE

AN1134

77-12-06 BY

Check H5 AIRCRAFT

ANNUAL/100 HRS. INSPECTION
FOUND IT AIRWORTHY

TACH *30352* TSMOHT *11*

DATE *12-9-88* *[Signature]* *2405258701A*

SERVICEABLE TAG

Northwest Propeller Service, Inc.

2131 E. St. N.E. • Auburn, WA 98002

REPAIR STATION NO. S61-89

T.S.O. *00100* T.T.

MFG. *Hamilton*

MODEL NO. *BHC-C2YF-2CLKF*

SERIAL NO. *AN1134*

BLADE MOD. NO. *F-JC8459-8R*

BLADE SERIAL NO. 1 *C72698*

2. *C72744* 3. *-* 4. *-*

REMARKS: *Complete overhaul of propeller per Hamilton*

measured #11707 #1338, installed

new device, both per H-5-2,

CPU 4297-12-06, Y-Hung 15185

1182, #1362 #1518, #155, +

312 #1447,

MECHANIC

DATE

[Signature]
7-13-89

DATE

3-13-89

30

T.S.O.

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-10-89			
		I CERTIFY AS OF THIS DATE THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>ANN</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 100 TACH TIME 3133	
6-23-89		1A 1522953 <i>Samuel D Wright</i>	
		I CERTIFY AS OF THIS DATE THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>ANN</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 200 TACH TIME 3233	
		1A 1522953 <i>Samuel D Wright</i>	

18

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Oct 16 Oct 16-89			
		I CERTIFY AS OF THIS DATE THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>abnormal</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME 5104 TACH TIME 3339.3	
		1A 1522953 <i>Samuel D Wright</i>	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-12-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>50 Hr</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>450.0</u> TACH TIME <u>3440</u> LA 1522953 <i>Donald D Wright</i>	<i>Prop</i> I CERTIFY AS OF THIS DATE THAT THIS HAS BEEN INSPECTED IN ACCORDANCE WITH INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>503.0</u> TACH TIME <u>3640.94</u> LA 1522953 <i>Donald D Wright</i>
7-11-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>100 Hr</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>507.0</u> TACH TIME <u>3540.0</u> <u>5 Hr</u> LA 1522953	<i>Prop</i> I CERTIFY AS OF THIS DATE THAT THIS HAS BEEN INSPECTED IN ACCORDANCE WITH INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>503.0</u> TACH TIME <u>3640.94</u> LA 1522953 <i>Donald D Wright</i>

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
2-19-90		I CERTIFY AS OF THIS DATE THAT THIS <u>PROP</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>ANP</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>400</u> TACH TIME <u>3440</u> LA 1522953 <i>Donald D Wright</i>	<i>Prop</i> I CERTIFY AS OF THIS DATE THAT THIS HAS BEEN INSPECTED IN ACCORDANCE WITH INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. TOTAL TIME <u>553.0</u> TACH TIME <u>3580.4</u> LA 1522953 <i>Donald D Wright</i>

DA
4-



LITHO U.S.A.

Memphis Propeller Service
FAA Approved No. 710-21
Dewitt Spain Airport
2787 N. Second St.
Memphis, Tenn. 38127

Silver Eagle Aircraft Inc.
Customer

Hartzell propeller
Item

WC-24F-2CHKF

Model

AN 1134

Serial Number

"The propeller, or component above
was **OVERHAULED** and inspected in
accordance with current Regulation
of the Federal Aviation Agency and
is approved for return to service."
Details of the work accomplished c
file at this repair station.

W/O *3599* Date *11-29-82*

Signed *W. J. Long*
Authorized Signature

OVERHAUL