

2022 Annual Inspection

Aircraft

St. Charles Flying Service, Inc

6016 Portage Rd Portage De Sioux MO 63373 (1-800-447-6066)
N5400B Date: 1/27/22 Tach: 1415.24 ACTIS: 2748.85
Airframe Model: Cessna 182 S/N: 18233400

1. Inspected aircraft per 14CFR43 App. D and Cessna 182 inspection guide.
2. Checked AD's
3. AD84-13-01R1 (07-05-88), fuel bladder/quick drains, complied with by inspection of fuel caps, fuel tank necks, and sump drains. Next due: 1/23.
4. AD11-10-09 (06-11-15), seats/tracks, complied with by visual inspection and dimensional measurements. Next due: 2848.85 ACTIS or 1/23.
5. C/W 91.207(d) ELT test and inspection. Next inspection due: 1/23. Battery due: 9/23.
6. Replaced induction filter with new
7. Found crack and stop drilled in lower, Pilot's side firewall and lower fwd skin at steering rod boot location. Performed hidden damage inspection during which no structural damage was noted. Recommend visual inspections at normal inspection intervals to monitor
8. Resealed LH brake piston and serviced brakes
9. Serviced nose strut
10. Replaced seat belt attachment hardware as needed
11. C/W ICA's as needed

I certify this aircraft has been inspected in accordance with an Annual inspection and was determined to be in Airworthy condition.

[Signature]
Clinton A Grant AP4948649591A

Engine

St. Charles Flying Service, Inc

6016 Portage Rd Portage De Sioux MO 63373 (1-800-447-6066)
N5400B Date: 1/27/22 Tach: 1415.24 SMOH: 89.49 ENG TIS: 3387.45
Engine Model: 0-470-L S/N: 48356-8-K-L

1. Drained oil. Removed and inspected screen. Cleaned and reinstalled screen with new gasket
2. Compression test: #1-70/80, #2-64/80, #3-76/80, #4-75/80, #5-66/80, #6-74/80
3. Cleaned, gapped, tested, and rotated spark plugs
4. Checked mag timing
5. Installed spark plugs with new gaskets and torqued
6. Serviced engine with 12qts Phillips 20W50X/C
7. Performed operational/leak check

I certify this engine has been inspected in accordance with a 100hr inspection and was determined to be in Airworthy condition.

[Signature]
Clinton A Grant AP4948649591A

Page No. Prop

DATE	TOTAL TACH	TOTAL	TACH OR	RMING WORK
			St. Charles Flying Service, Inc	
			6016 Portage Rd Portage De Sioux MO 63373 (1-800-447-6066)	
			N5400B Date: 1/27/22 Tach: 1415.24 Prop TIS: 556.79	
			Propeller Model: 2A34C203-C S/N: 992206	
			1. Removed spinner.	
			2. Inspected prop, spinner, and bulkheads.	
			3. Reinstalled spinner.	
			4. I certify this propeller has been inspected in accordance with a 100hr inspection and was determined to be in Airworthy condition.	
			Clinton A Grant AP4948649591A	