## PROPELLER LOG BOOK



## SENSENICH WOOD PROPELLER CO., INC. PLANT CITY, FL

www.sensenichprop.com

This log book is to be kept with the propeller for recording of all propeller maintenance performed

### **Propeller Maintenance Record**

Propeller Model Number W72GK46

Propeller Serial Number AK 4322

TG782 PC335CE

Size of Steel Aircraft Bolt		Recommended Wrench Torque Range			
Spec.	Dia. (in.)	inlb.	ftlb.	nm.	
AN4	1/4	120 to 140	10 to 12	14 to 16	
AN5	5/16	130 to 160	11 to 13	15 to 18	
AN6	3/8	175 to 225	15 to 19	20 to 25	
AN7	7/16	225 to 275	19 to 23	25 to 31	
AN8	1/2	275 to 325	23 to 27	31 to 37	
AN10	5/8	325 to 375	27 to 31	37 to 42	

# DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS AND MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-21-15	19.9	INSTALLED PROD	PARRICH TRAVERY
	TTP"0"		THE TOTAL PROPERTY.

09/05/15 N93985 Ercoupe 415C Sensenich Model W72GK46 S/N AK4322 Tach 20.5 TTP 0.6

Comply with Annual inspection per scope and details of FAR 43 Appendix D. Check blades for condition. Retorque prop bolts per manufactures spec's. Ground run found blades track normal. AD's checked thru this date and complied with as noted. I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in an Airworthy condition on this date.

Air Professionals 17416 Airfield Ln Pearland,Tx 77581 (281) 992-3484

Randy Wahlberg A&P 3563642IA

Kana Wohle

#### VIATURI Propeller

DATE			MODEL: Sensenich W72GK46 S/N: AK4322	PTSOH: 73.0 Tach: 92.9	Date: 8 Oct 2024 Reg. N93985	URE
	Annual ir	dge of both spection a	nspection IAW FAR 43 and spinner assembly. In propeller blades, This not found to be in Un-Ai	propeller has be rworthy condition	Cracks on motal	
				·		